

2005 Lexus LS430

Lexus service history | Stock 3704

VIN: JTHBN36F055013704

Readable PDF export prepared by Tanin JDM from the supplied Lexus service-history document. Records span March 2005 through July 2023. This export preserves the source entries, including original abbreviations, spelling, declined work, and recommendations. It is not a new inspection or an independently issued Lexus report. Two phone-number occurrences were omitted; service content is unchanged.

7/24/2023 (159595 miles)

REPAIR NUMBER: 0113794

REPORTED BY: Lexus of Glendale

SERVICE: GUEST IS TOWING IN LEXUS VEHICLE

DESCRIPTION: ~|~GUEST IS TOWING IN LEXUS VEHICLE ~|~NOTE

SERVICE: REPLACED ALTERNATOR WITH DRIVE BELT (GUEST DECLINED TIMING BELT PACKAGE)

DESCRIPTION: ~|~GUEST STATES CHECK ENGINE WARNING LIGHT IS ON. PLEASE INSPECT AND ADVISE AND WILL NOT STAY RUNNING ~|~GUEST STATES CHECK ENGINE WARNING LIGHT IS ON. PLEASE INSPECT AND ADVISE

SERVICE: PERFORM COMPLIMENTARY MULTI POINT INSPECTION

DESCRIPTION: ~|~PERFORM COMPLIMENTARY MULTI POINT INSPECTION ~|~

SERVICE: PERFORM LEXUS LUXURY CARE VEHICLE INSPECTION

DESCRIPTION:

SERVICE: INSPECT DRIVERS SIDE FLOOR MAT FOR PROPER INSTALLATION

DESCRIPTION:

SERVICE: TIRE PRESSURE CHECK AND INFLATE SERVICE

DESCRIPTION:

SERVICE:

DESCRIPTION: YOU CONSENT TO RECEIVING TEXTS FROM US ON YOUR CELL PHONE AT THE NUMBER YOU HAVE PROVIDED. YOU AGREE

SERVICE: REPLACE FRONT BRAKE PADS AND RESURFACE ROTORS.

DESCRIPTION: ~|~REPLACE FRONT BRAKE PADS AND RESURFACE ROTORS. ~|~

8/9/2021 (153962 miles)

REPAIR NUMBER: 0046334

REPORTED BY: Lexus of Glendale

SERVICE: PERFORM ROUTINE MAINTENANCE

DESCRIPTION: ~|~PERFORM ROUTINE MAINTENANCE 155,000 MINIMUM RECOMMENDED SERVICES \$ 251.13
REPLACE ENGINE OIL AND OIL FILTER ROTATE TIRES AND ADJUST TIRE PRESSURE AS NEEDED VISUALLY
INSPECT BRAKE PADS AND BRAKE ROTORS RE-TORQUE DRIVE SHAFT FLANGE BOLTS INSPECT ENGINE COOL
~|~

SERVICE: PERFORM COMPLIMENTARY MULTI POINT INSPECTION

DESCRIPTION: ~|~PERFORM COMPLIMENTARY MULTI POINT INSPECTION ~|~

SERVICE: PERFORM LEXUS LUXURY CARE VEHICLE INSPECTION

DESCRIPTION:

SERVICE: INSPECT DRIVERS SIDE FLOOR MAT FOR PROPER INSTALLATION

DESCRIPTION:

SERVICE: TIRE PRESSURE CHECK AND INFLATE SERVICE

DESCRIPTION:

SERVICE:

DESCRIPTION: YOU CONSENT TO RECEIVING TEXTS FROM US ON YOUR CELL PHONE AT THE NUMBER YOU
HAVE PROVIDED. YOU AGREE

SERVICE: GUEST INFORMATION HAS BEEN INPUT FOR LOANER

DESCRIPTION: ~|~GUEST INFORMATION HAS BEEN INPUT FOR LOANER ~|~GUEST INFORMATION HAS BEEN
INPUT

7/21/2019 (148495 miles)

REPAIR NUMBER: 0064453

REPORTED BY: Lexus of Glendale

SERVICE: SET TIRE PRESSURE AND RESET SYSTEM

DESCRIPTION: ~|~GUEST STATES THAT THE TIRE LIGHT IS ON ~|~ ~|~SET TIRE PRESSURE AND RESET SYSTEM

SERVICE: PERFORMED 30,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 150,000 MILES SERVICE ~|~ ~|~PERFORMED 30,000 MILES SERVICE

SERVICE: REPLACED CABIN(AIR CONDITIONING) FILTER

DESCRIPTION: ~|~REPLACE CABIN(AIR CONDITIONING) FILTER ~|~ ~|~REPLACED CABIN(AIR CONDITIONING)
FILTER

SERVICE: INSPECTED DRIVER'S FLOOR MAT FOR PROPER INSTALLATION

DESCRIPTION: ~|~INSPECT DRIVER'S FLOOR MAT FOR PROPER INSTALLATION ~|~ ~|~INSPECTED DRIVER'S
FLOOR MAT FOR PROPER INSTALLATION

SERVICE: RF33- PSI,LF33- PSI,RR33- PSI,LR33- PSI.AMBIENT TEMP80- DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF33- PSI,LF33- PSI,RR33- PSI,LR33-
PSI.AMBIENT TEMP80- DEG. FAHRENHEIT

8/5/2018 (143489 miles)

REPAIR NUMBER: 0024061

REPORTED BY: Lexus of Glendale

SERVICE: PERFORMED 140,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 140,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 140,000 MILES SERVICE

SERVICE: RECOMMEND TO REPLACE REAR SUNSHADE

DESCRIPTION: ~|~GUEST STATES REAR SUNSCREEN SHADES GETS STUCK OFF AN ON. PLEASE CHECK AND ADVISE ~|~FOUND REAR SUNSHADE BINDING ~|~RECOMMEND TO REPLACE REAR SUNSHADE

SERVICE: REPLACE FRONT ENGINE MOUNTS

DESCRIPTION: ~|~GUEST AUTHORIZED TO REPLACE FRONT ENGINE MOUNTS ~|~FOUND FRONT ENGINE MOUNT INSULATORS WEAK/COMING APART ~|~REPLACE FRONT ENGINE MOUNTS

SERVICE: REPLACED TRANSMISSION MOUNT

DESCRIPTION: ~|~GUEST AUTHORIZED TO REPLACE TRANSMISSION MOUNT ~|~FOUND TRANSMISSION MOUNT INSULATOR WORN/ COMING APART ~|~REPLACED TRANSMISSION MOUNT

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: INSPECTED DRIVER'S FLOOR MAT FOR PROPER INSTALLATION

DESCRIPTION: ~|~INSPECT DRIVER'S FLOOR MAT FOR PROPER INSTALLATION ~|~ ~|~INSPECTED DRIVER'S FLOOR MAT FOR PROPER INSTALLATION

SERVICE: RF -35 PSI,LF -35 PSI,RR -35 PSI,LR -35 PSI.AMBIENT TEMP -70 DEG. FAHRENH

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF -35 PSI,LF -35 PSI,RR -35 PSI,LR -35 PSI.AMBIENT TEMP -70 DEG. FAHRENHEIT

10/9/2017 (138400 miles)

REPAIR NUMBER: 0086215

REPORTED BY: Lexus of Glendale

SERVICE: INSPECTED DRIVER'S FLOOR MAT FOR PROPER INSTALLATION

DESCRIPTION: ~|~INSPECT DRIVER'S FLOOR MAT FOR PROPER INSTALLATION ~|~ ~|~INSPECTED DRIVER'S FLOOR MAT FOR PROPER INSTALLATION

SERVICE: PERFORMED 135,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 135,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 135,000 MILES SERVICE

SERVICE: RF -34 PSI,LF -34 PSI,RR -34 PSI,LR -34 PSI.AMBIENT TEMP-70 DEG. FAHRENHE

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF -34 PSI,LF -34 PSI,RR -34 PSI,LR -34 PSI.AMBIENT TEMP-70 DEG. FAHRENHEIT

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

11/30/2016 (133378 miles)

REPAIR NUMBER: 0046075

REPORTED BY: Lexus of Glendale

SERVICE: INSPECTED DRIVER'S FLOOR MAT FOR PROPER INSTALLATION

DESCRIPTION: ~|~INSPECT DRIVER'S FLOOR MAT FOR PROPER INSTALLATION ~|~ ~|~INSPECTED DRIVER'S FLOOR MAT FOR PROPER INSTALLATION

SERVICE: THANK YOU

DESCRIPTION: ~|~THANK YOU FOR MAKING YOUR APPOINTMENT WITH LEXUS OF GLENDALE ~|~ ~|~THANK YOU

SERVICE: PERFORMED 10,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 10,000 MILES SERVICE ~|~ ~|~PERFORMED 10,000 MILES SERVICE

SERVICE: RF35- PSI,LF-35 PSI,RR-35 PSI,LR35- PSI.AMBIENT TEMP- DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF35- PSI,LF-35 PSI,RR-35 PSI,LR35- PSI.AMBIENT TEMP- DEG. FAHRENHEIT

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: REPLACED REAR BRAKE PADS AND RESURFACED BRAKE ROTORS

DESCRIPTION: ~|~REAR BRAKE JOB, INCLS. REFACING, W/O HARDWARE, R&R ~|~ ~|~REPLACED REAR BRAKE PADS AND RESURFACED BRAKE ROTORS

SERVICE: REPLACED FRONT BRAKE PADS AND RESURFACED BRAKE ROTORS

DESCRIPTION: ~|~REPLACE FRONT BRAKES ~|~ ~|~REPLACED FRONT BRAKE PADS AND RESURFACED BRAKE ROTORS

SERVICE: COMPLETED

DESCRIPTION: ~|~REPLACE BATTERIES IN ATTACHED KEYS ~|~ ~|~COMPLETED

SERVICE: REPLACE RADIATOR CAP

DESCRIPTION: ~|~REPLACE RADIATOR CAP ~|~ ~|~REPLACE RADIATOR CAP

3/16/2016 (128688 miles)

REPAIR NUMBER: 0015335

REPORTED BY: Lexus of Glendale

SERVICE: INSPECTED DRIVER'S FLOOR MAT FOR PROPER INSTALLATION

DESCRIPTION: ~|~INSPECT DRIVER'S FLOOR MAT FOR PROPER INSTALLATION ~|~ ~|~INSPECTED DRIVER'S FLOOR MAT FOR PROPER INSTALLATION

SERVICE: ERFORMED 5,000 MILES SERVICE "125000MILES SERVICE

DESCRIPTION: P" ~|~PERFORM 5,000 MILES SERVICE "125000MILES SERVICE" ~|~AS RECOMMENDED ~|~PERFORMED 5,000 MILES SERVICE "125000MILES SERVICE"

SERVICE: RF- 36 PSI,LF- 36 PSI,RR- 36 PSI,LR- 36 PSI.AMBIENT TEMP- 82 DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF- 36 PSI,LF- 36 PSI,RR- 36 PSI,LR- 36 PSI.AMBIENT TEMP- 82 DEG. FAHRENHEIT

SERVICE: MAY NEED FRONT AND REAR BRAKE PADS ON NEXT SERVICE.

DESCRIPTION: ~|~NOTE: MAY NEED FRONT AND REAR BRAKE PADS ON NEXT SERVICE. ~|~ ~|~MAY NEED FRONT AND REAR BRAKE PADS ON NEXT SERVICE.,CUSTOMER DECLINED SERVICE -RECOMMENDED, NOT DONE-MAY

NEED FRONT AND REAR BRAKE PADS ON NEXT SERVICE.

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: RESEAL FREEZE PLUG

DESCRIPTION: ~|~UPON INSPECTION, GUEST AUTHORIZE TO REPLACE FREEZE PLUG ~|~FOUND FREEZE PLUG
LEAKING COOLANT OUT. ~|~RESEAL FREEZE PLUG

SERVICE: R&R TRANSMISSION PAN GASKET

DESCRIPTION: ~|~UPON INSPECTION, GUEST AUTHORIZE TOR REPLACE TRANSMISSION PAN GASKET
~|~FOUND TRANSMISSION PAN GASKET LEAKING FLUID OUT. ~|~R&R TRANSMISSION PAN GASKET

10/22/2015 (123543 miles)

REPAIR NUMBER: 0098890

REPORTED BY: Lexus of Glendale

SERVICE: INSPECTED DRIVER'S FLOOR MAT FOR PROPER INSTALLATION

DESCRIPTION: ~|~INSPECT DRIVER'S FLOOR MAT FOR PROPER INSTALLATION ~|~ ~|~INSPECTED DRIVER'S
FLOOR MAT FOR PROPER INSTALLATION

SERVICE: RF- 34 PSI,LF- 34 PSI,RR- 34 PSI,LR- 34 PSI.AMBIENT TEMP- 82 DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF- 34 PSI,LF- 34 PSI,RR- 34 PSI,LR- 34
PSI.AMBIENT TEMP- 82 DEG. FAHRENHEIT

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: PERFORMED 120,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 120,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 120,000 MILES
SERVICE

SERVICE: R&R BOTH FRONT ENGINE MOUNT ASSEMBLIES.

DESCRIPTION: ~|~UPON INSPECTION, GUEST AUTHORIZE TO REPLACE BOTH FRONT ENGINE MOUNTS.
~|~FOUND ENGINE MOUNTS ARE CRACKED ~|~R&R BOTH FRONT ENGINE MOUNT ASSEMBLIES.

SERVICE: REPLACE REAR TRANS MOUNT ASSEMBLY.

DESCRIPTION: ~|~UPON INSPECTION, GUEST AUTHORIZE TO REPLACE REAR TRANS MOUNT ~|~FOUND REAR
TRANS MOUNT WORN OUT. ~|~REPLACE REAR TRANS MOUNT ASSEMBLY.

SERVICE: PERFORM POWER STEERING FLUID EXCHANGE.

DESCRIPTION: ~|~UPON INSPECTION, GUEST AUTHORIZE TO PERFORM POWER STEERING FLUID EXCHANGE.
~|~FOUND POWER STEERING FLUID IS DISCOLORED. ~|~PERFORM POWER STEERING FLUID EXCHANGE.

2/11/2015 (118556 miles)

REPAIR NUMBER: 0070207

REPORTED BY:

SERVICE: INSPECTED DRIVER'S FLOOR MAT FOR PROPER INSTALLATION

DESCRIPTION: ~|~INSPECT DRIVER'S FLOOR MAT FOR PROPER INSTALLATION ~|~ ~|~INSPECTED DRIVER'S
FLOOR MAT FOR PROPER INSTALLATION

SERVICE: THANK YOU

DESCRIPTION: ~|~THANK YOU FOR MAKING YOUR APPOINTMENT WITH LEXUS OF GLENDALE ~|~ ~|~THANK YOU

SERVICE: PERFORMED 115,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 115,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 115,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: PERFORMED 4 WHEEL ALIGNMENT

DESCRIPTION: ~|~PREVENTATIVE MAINTENANCE ALIGNMENT ~|~ ~|~PERFORMED 4 WHEEL ALIGNMENT

SERVICE: RF- 33 PSI,LF- 33 PSI,RR- 33 PSI,LR- 33 PSI.AMBIENT TEMP- 74 DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF- 33 PSI,LF- 33 PSI,RR- 33 PSI,LR- 33 PSI.AMBIENT TEMP- 74 DEG. FAHRENHEIT

SERVICE: REPLACE BOTH FRONT WIPER INSERTS.

DESCRIPTION: ~|~UPON INSPECTION, GUEST AUTHORIZE TO REPLACE FRONT WIPER INSERTS. ~|~UPON INSPECTION, FOUND FRONT WIPER INSERTS ARE TORN AND WORN. ~|~REPLACE BOTH FRONT WIPER INSERTS.

8/18/2014 (113062 miles)

REPAIR NUMBER: 0051368

REPORTED BY:

SERVICE: PERFORMED 110,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 110,000 MILES SERVICE ~|~ ~|~PERFORMED 110,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: RECOMMEND HOOD AND TRUNK SUPPORTS

DESCRIPTION: ~|~NOTE: ~|~ ~|~RECOMMEND HOOD AND TRUNK SUPPORTS,CUSTOMER DECLINED SERVICE -RECOMMENDED, NOT DONE-RECOMMEND HOOD AND TRUNK SUPPORTS

SERVICE: RF38- PSI,LF-38 PSI,RR-38 PSI,LR38- PSI.AMBIENT TEMP- DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF38- PSI,LF-38 PSI,RR-38 PSI,LR38- PSI.AMBIENT TEMP- DEG. FAHRENHEIT

SERVICE: REPLACE LEFT FRONT MARKER BULB

DESCRIPTION: ~|~REPLACE LEFT FRONT MARKER BULB ~|~ ~|~REPLACE LEFT FRONT MARKER BULB

2/11/2014 (108025 miles)

REPAIR NUMBER: 0032277

REPORTED BY:

SERVICE: THANK YOU

DESCRIPTION: ~|~THANK YOU FOR MAKING YOUR APPOINTMENT WITH LEXUS OF GLENDALE ~|~ ~|~THANK YOU

SERVICE: RF-35 PSI,LF- 35 PSI,RR-35 PSI,LR-35 PSI.AMBIENT TEMP- DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF-35 PSI,LF- 35 PSI,RR-35 PSI,LR-35 PSI.AMBIENT TEMP- DEG. FAHRENHEIT

SERVICE: PERFORMED 105,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 105,000 MILES SERVICE ~|~ ~|~PERFORMED 105,000 MILES SERVICE

SERVICE: SHUTTLE SERVICE

DESCRIPTION: ~|~GUEST REQUESTS SHUTTLE SERVICE ~|~ ~|~SHUTTLE SERVICE

SERVICE: RECOMMEND WIPERS AND HOOD SHOCKS

DESCRIPTION: ~|~NOTE: ~|~ ~|~RECOMMEND WIPERS AND HOOD SHOCKS,CUSTOMER DECLINED SERVICE
-RECOMMENDED, NOT DONE-RECOMMEND WIPERS AND HOOD SHOCKS

SERVICE: PLEASE REPLACE BATTERY IN REMOTE

DESCRIPTION: ~|~PLEASE REPLACE BATTERY IN REMOTE ~|~ ~|~PLEASE REPLACE BATTERY IN REMOTE

SERVICE: NO REPAIRS NEEDED, RECOMMENDED OR PERFORMED AT THIS TIME.

DESCRIPTION: ~|~GUEST STATES THAT THERE IS A WIGGLING TYPE SOUND FROM THE RT FRONT-ADVISE ~|~
~|~NO REPAIRS NEEDED, RECOMMENDED OR PERFORMED AT THIS TIME.

10/13/2013 (102738 miles)

REPAIR NUMBER: 0020264

REPORTED BY:

SERVICE: THANK YOU

DESCRIPTION: ~|~THANK YOU FOR MAKING YOUR APPOINTMENT WITH LEXUS OF GLENDALE ~|~ ~|~THANK YOU

SERVICE: RF-36 PSI,LF-36 PSI,RR-36 PSI,LR-36 PSI.AMBIENT TEMP- DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF-36 PSI,LF-36 PSI,RR-36 PSI,LR-36
PSI.AMBIENT TEMP- DEG. FAHRENHEIT

SERVICE: PERFORMED 100,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 100,000 MILES SERVICE ~|~ ~|~PERFORMED 100,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

DESCRIPTION: ~|~[phone number omitted] ~|~ ~|~THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

5/30/2013 (97460 miles)

REPAIR NUMBER: 0007772

REPORTED BY:

SERVICE: THANK YOU

DESCRIPTION: ~|~THANK YOU FOR MAKING YOUR APPOINTMENT WITH LEXUS OF GLENDALE ~|~ ~|~THANK YOU

SERVICE: PERFORMED 95,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 95,000 MILES SERVICE ~|~ ~|~PERFORMED 95,000 MILES SERVICE

SERVICE: HOOD SHOCKS ARE WEAK

DESCRIPTION: ~|~NOTE: ~|~ ~|~CUSTOMER DENIED SERVICE - RECOMMENDED, NOT DONE-HOOD SHOCKS ARE
WEAK

SERVICE: RF36 PSI,LF-36PSI,RR- 36SI,LR-36PSI.AMBIENT TEMP- DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF36 PSI,LF-36PSI,RR-
36SI,LR-36PSI.AMBIENT TEMP- DEG. FAHRENHEIT

SERVICE: THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

DESCRIPTION: ~|~[phone number omitted] ~|~ ~|~THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

1/17/2013 (92258 miles)

REPAIR NUMBER: 0095298

REPORTED BY:

SERVICE: RF-34 PSI,LF-34 PSI,RR- 34 PSI,LR-34 PSI.AMBIENT TEMP-68 DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF-34 PSI,LF-34 PSI,RR- 34 PSI,LR-34 PSI.AMBIENT TEMP-68 DEG. FAHRENHEIT

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

DESCRIPTION: ~|~LEXUS OF GLENDALE SERVICE ~|~ ~|~THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

SERVICE: REPLACED FRONT BRAKE PADS AND RESURFACED BRAKE ROTORS

DESCRIPTION: ~|~REPLACE FRONT BRAKE PADS AND MACHINE FRONT ROTORS. FRONT BRAKE PADS WORN DOWN TO 3MM, MIN SPEC-3MM ~|~ ~|~REPLACED FRONT BRAKE PADS AND RESURFACED BRAKE ROTORS

SERVICE: PERFORMED 90,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 90,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 90,000 MILES SERVICE

9/9/2012 (87229 miles)

REPAIR NUMBER: 0081829

REPORTED BY:

SERVICE: THANK YOU

DESCRIPTION: ~|~THANK YOU FOR MAKING YOUR APPOINTMENT WITH LEXUS OF GLENDALE ~|~ ~|~THANK YOU

SERVICE: PERFORMED 85,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 85,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 85,000 MILES SERVICE

SERVICE: RF-34 PSI,LF-34 PSI,RR-34 PSI,LR-34 PSI.AMBIENT TEMP-70 DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF-34 PSI,LF-34 PSI,RR-34 PSI,LR-34 PSI.AMBIENT TEMP-70 DEG. FAHRENHEIT

SERVICE: TECH RECOMMENATIONS: REPLACE 4 TIRES (BALD AND SPLITTING ON INSIDE SHOULDER),

DESCRIPTION: ~|~NOTE: ~|~ ~|~CUSTOMER DENIED SERVICE - RECOMMENDED, NOT DONE-TECH

RECOMMENATIONS: REPLACE 4 TIRES (BALD AND SPLITTING ON INSIDE SHOULDER), BATTERY // GUEST DECLINED REPAIRS

SERVICE: THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

DESCRIPTION: ~|~LEXUS OF GLENDALE SERVICE ~|~ ~|~THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

5/14/2012 (81721 miles)

REPAIR NUMBER: 0070045

REPORTED BY:

SERVICE: RF-34 PSI,LF-34 PSI,RR-34 PSI,LR-34 PSI.AMBIENT TEMP-67F DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF-34 PSI,LF-34 PSI,RR-34 PSI,LR-34 PSI.AMBIENT TEMP-67F DEG. FAHRENHEIT

SERVICE: PERFORMED 80,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 80,000 MILES SERVICE ~|~ ~|~PERFORMED 80,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: GUEST DECLINED REPAIRS 94 TIRES AND ALIGNMENT)

DESCRIPTION: ~|~GUEST DECLINED REPAIRS ~|~ ~|~GUEST DECLINED REPAIRS 94 TIRES AND ALIGNMENT)

SERVICE: REPLACED REAR BRAKES, MACHINE ROTORS

DESCRIPTION: ~|~REPLACE REAR BRAKES AND MACHINE ROTORS ~|~ ~|~REPLACED REAR BRAKES, MACHINE ROTORS

1/5/2012 (75706 miles)

REPAIR NUMBER: 0056813

REPORTED BY:

SERVICE: RF-36 PSI,LF-36 PSI,RR-36 PSI,LR-36 PSI.AMBIENT TEMP-67F DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF-36 PSI,LF-36 PSI,RR-36 PSI,LR-36 PSI.AMBIENT TEMP-67F DEG. FAHRENHEIT

SERVICE: PERFORMED 75,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 75,000 MILES SERVICE ~|~ ~|~PERFORMED 75,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: 4 TIRES AND ALIGNMENT

DESCRIPTION: ~|~NOTE: ~|~ ~|~CUSTOMER DENIED SERVICE - RECOMMENDED, NOT DONE-4 TIRES AND ALIGNMENT

SERVICE: RESCUED COIN HOLDET IT IS OK AT THIS TIME

DESCRIPTION: ~|~GUEST STATES COIN HOLDER WONT OPEN ~|~ ~|~RESCUED COIN HOLDET IT IS OK AT THIS TIME

SERVICE: REINSTALLED CLIPS

DESCRIPTION: ~|~GUEST STATES RIGHT FRONT BUMPER COVER IS LOOSE ~|~ ~|~REINSTALLED CLIPS

SERVICE: PERFORMED T-BELT PACKAGE

DESCRIPTION: ~|~PERFORM T-BELT PACKAGE ~|~ ~|~PERFORMED T-BELT PACKAGE

SERVICE: REPLACED BOTH ENGINE MOUNTS

DESCRIPTION: ~|~REPLACE BOTH ENGINE MOUNTS ~|~ ~|~REPLACED BOTH ENGINE MOUNTS

9/7/2011 (70357 miles)

REPAIR NUMBER: 0045344

REPORTED BY:

SERVICE: RF-34 PSI,LF-34 PSI,RR-34 PSI,LR-34 PSI.AMBIENT TEMP-82 DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF-34 PSI,LF-34 PSI,RR-34 PSI,LR-34 PSI.AMBIENT TEMP-82 DEG. FAHRENHEIT

SERVICE: PERFORMED 70,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 70,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 70,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: SEE ATTACHED INSPECTION FORM

DESCRIPTION: ~|~PERFORM LEXUS LUXURY CARE VEHICLE INSPECTION ~|~LLC ~|~SEE ATTACHED INSPECTION FORM

5/9/2011 (65222 miles)

REPAIR NUMBER: 0032862

REPORTED BY:

SERVICE: RF-33 PSI,LF-33 PSI,RR-33 PSI,LR-33 PSI.AMBIENT TEMP-78F DEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF-33 PSI,LF-33 PSI,RR-33 PSI,LR-33 PSI.AMBIENT TEMP-78F DEG. FAHRENHEIT

SERVICE: PERFORMED 65,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 65,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 65,000 MILES SERVICE

12/7/2010 (60083 miles)

REPAIR NUMBER: 0016119

REPORTED BY:

SERVICE: RF-33PSI,LF-33PSI,RR-33PSI,LR -33PSI.AMBIENT TEMP-80FEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF-33PSI,LF-33PSI,RR-33PSI,LR -33PSI.AMBIENT TEMP-80FEG. FAHRENHEIT

SERVICE: PROGRAMED TWO MASTER KEYS

DESCRIPTION: ~|~GUETS REQUESTS TO PROGRAM TWO MASTER KEYS ~|~ ~|~PROGRAMED TWO MASTER KEYS

12/6/2010 (60082 miles)

REPAIR NUMBER: 0015992

REPORTED BY:

SERVICE: RF-33PSI,LF-33PSI,RR-33PSI,LR -33PSI.AMBIENT TEMP-68FEG. FAHRENHEIT

DESCRIPTION: ~|~TIRE PRESSURE CHECK AND INFLATE SERVICE ~|~ ~|~RF-33PSI,LF-33PSI,RR-33PSI,LR -33PSI.AMBIENT TEMP-68FEG. FAHRENHEIT

SERVICE: PERFORMED 60,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 60,000 MILES SERVICE ~|~AS RECOMMENDDE ~|~PERFORMED 60,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: PERFORMED REPLACED BATTERY ON BOTH MASTER KEYS

DESCRIPTION: ~|~GUEST REQUESTS TO REPLACE BATTERY ON BOTH MASTER KEYS ~|~ ~|~PERFORMED REPLACED BATTERY ON BOTH MASTER KEYS

2/25/2010 (54925 miles)

REPAIR NUMBER: 0084302

REPORTED BY:

SERVICE: PERFORMED 55,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 55,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 55,000 MILES SERVICE

SERVICE: PERFORMED 4 WHEEL ALIGNMENT

DESCRIPTION: ~|~ALIGNMENT ~|~ ~|~PERFORMED 4 WHEEL ALIGNMENT

SERVICE: LEXUS WIPER INSERTS INSTALLED

DESCRIPTION: ~|~INSTALL LEXUS WIPER INSERTS QTY 2 ~|~ ~|~LEXUS WIPER INSERTS INSTALLED

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: REPLACED LOWER CONTROL ARM BUSHINGS

DESCRIPTION: ~|~GUEST REQUESTS TO REPLACE LOWER CONTROL ARM BUSHINGS ~|~ ~|~REPLACED LOWER CONTROL ARM BUSHINGS

SERVICE: CUT AND PROGRAMMED ONE MASTER KEY

DESCRIPTION: ~|~GUEST REQUESTS 1 MASTER KEY ~|~ ~|~CUT AND PROGRAMMED ONE MASTER KEY

5/26/2009 (49608 miles)

REPAIR NUMBER: 0053697

REPORTED BY:

SERVICE: PERFORMED 50,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 50,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 50,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

DESCRIPTION: ~|~LEXUS OF GLENDALE SERVICE ~|~ ~|~THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

12/8/2008 (45636 miles)

REPAIR NUMBER: 0034289

REPORTED BY:

SERVICE: PERFORMED 45,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 45,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 45,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

DESCRIPTION: ~|~LEXUS OF GLENDALE SERVICE ~|~ ~|~THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

SERVICE: REPLACED FRONT BRAKES, MACHINE ROTORS WITH CALIPER BOLTS

DESCRIPTION: ~|~REPLACE FT. BRAKE AND MACHINE ROTORS WITH CALIPER BOLTS/GUEST APPROVED \$346
~|~ ~|~REPLACED FRONT BRAKES, MACHINE ROTORS WITH CALIPER BOLTS

7/13/2008 (40771 miles)

REPAIR NUMBER: 0016395

REPORTED BY:

SERVICE: PERFORMED 40,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 40,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 40,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

DESCRIPTION: ~|~LEXUS OF GLENDALE SERVICE ~|~ ~|~THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

SERVICE: OK AT THIS TIME / RESET PRESSURES TO SPECS AND REINITIALIZED TIRE PRESSURE SYSTE

DESCRIPTION: ~|~LOW TIRE LIGHT IS ON, PLEASE CHECK AND ADVISE ~|~FND TIRES HAVE LOW TIRE
PRESSURE AT THIS TIME ~|~OK AT THIS TIME / RESET PRESSURES TO SPECS AND REINITIALIZED TIRE
PRESSURE SYSTEM

1/28/2008 (35294 miles)

REPAIR NUMBER: 0095675

REPORTED BY:

SERVICE: PERFORMED 35,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 35,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 35,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

SERVICE: THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

DESCRIPTION: ~|~LEXUS OF GLENDALE SERVICE ~|~ ~|~THANK YOU FOR CHOOSING LEXUS OF GLENDALE!!

SERVICE: FND BOTH SMART KEYS IN VEHICLE - FND ONE UNDER DRIVER'S SEAT AT THIS TIME
DESCRIPTION: ~|~GUEST STATES LOCK/UNLOCK FUNCTION USING SMART KEY FUNCTION DOESN'T WORK --
CHECK AND ADVISE. ~|~ ~|~FND BOTH SMART KEYS IN VEHICLE - FND ONE UNDER DRIVER'S SEAT AT THIS TIME

SERVICE: APPLIED DISCOUNT AUTH PER MIKE OJ.
DESCRIPTION: ~|~APPLY 10% DISCOUNT PER MIKE O.J. ~|~ ~|~APPLIED DISCOUNT AUTH PER MIKE OJ.

8/30/2007 (30470 miles)

REPAIR NUMBER: 0077082
REPORTED BY:

SERVICE: PERFORMED 30,000 MILES SERVICE
DESCRIPTION: ~|~PERFORM 30,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 30,000 MILES
SERVICE

SERVICE: COURTESY LOANER CAR
DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

6/4/2007 (25439 miles)

REPAIR NUMBER: 0066086
REPORTED BY:

SERVICE: PERFORMED 25,000 MILES SERVICE
DESCRIPTION: ~|~PERFORM 25,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 25,000 MILES
SERVICE

SERVICE: REINSTALLED DOOR PANEL
DESCRIPTION: ~|~FRT. DRIVER INSIDE DOOR PANEL CAME LOOSE AND LOCATED IN THE FRT. PASS. SEAT --
CHECK AND ADVISE. ~|~ ~|~REINSTALLED DOOR PANEL

11/29/2006 (20472 miles)

REPAIR NUMBER: 0042820
REPORTED BY:

SERVICE: PERFORMED 20,000 MILES SERVICE
DESCRIPTION: ~|~PERFORM 20,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 20,000 MILES
SERVICE

8/22/2006 (15495 miles)

REPAIR NUMBER: 0030760
REPORTED BY:

SERVICE: BUDGET RENT A CAR
DESCRIPTION: ~|~BUDGET RENT A CAR ~|~BUDGET RENT A CAR ~|~BUDGET RENT A CAR

8/13/2006 (15494 miles)

REPAIR NUMBER: 0029607

REPORTED BY:

SERVICE: PERFORMED 15,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 15,000 MILES SERVICE ~|~ ~|~PERFORMED 15,000 MILES SERVICE

SERVICE: COURTESY LOANER CAR

DESCRIPTION: ~|~COURTESY LOANER CAR ~|~ ~|~COURTESY LOANER CAR

2/5/2006 (10056 miles)

REPAIR NUMBER: 0007363

REPORTED BY:

SERVICE: PERFORMED 10,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 10,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 10,000 MILES SERVICE

8/28/2005 (5082 miles)

REPAIR NUMBER: 0089666

REPORTED BY:

SERVICE: WARRANTY LOANER CAR

DESCRIPTION: ~|~WARRANTY LOANER CAR ~|~ ~|~WARRANTY LOANER CAR

SERVICE: PERFORMED 5,000 MILES SERVICE

DESCRIPTION: ~|~PERFORM 5,000 MILES SERVICE ~|~AS RECOMMENDED ~|~PERFORMED 5,000 MILES SERVICE

4/4/2005 (173 miles)

REPAIR NUMBER: 0072026

REPORTED BY:

SERVICE: MOBILE SERVICE APPOINTMENT COMPLETED.

DESCRIPTION: ~|~MOBILE SERVICE TO INSPECT VEHICLE AT HOME ADDRESS BETWEEN 11AM AND 12PM.
CONTACT CUSTOMER ON HIS CELL PHONE #. ~|~ ~|~MOBILE SERVICE APPOINTMENT COMPLETED.

SERVICE: PROGRAMMING OF HOME LINK COMPLETED

DESCRIPTION: ~|~PERFORM HOMELINK ~|~PER GUEST REQUEST ~|~PROGRAMMING OF HOME LINK COMPLETED

SERVICE: NO WORK DONE

DESCRIPTION: ~|~PERFORM C-BEST ~|~ ~|~NO WORK DONE

3/1/2005 (11 miles)

REPAIR NUMBER: 0068778

REPORTED BY:

SERVICE: PRE DELIVERY SERVICE COMPLETED

DESCRIPTION: ~|~PRE DELIVERY SERVICE ~|~ ~|~PRE DELIVERY SERVICE COMPLETED

SERVICE: DETAIL PERFORMED & INSTALL PLATES & FRAMES

DESCRIPTION: ~|~NEW & PRE-OWN DETAIL & INSTALL FRAMES / PLATES ~|~ ~|~DETAIL PERFORMED & INSTALL
PLATES & FRAMES