

# Lexus dealer service history

## 2006 Lexus LS430 ML | Stock 8676

VIN: JTHBN36F765048676

Full text of the supplied service-history document. One phone number has been omitted for privacy; service entries, recommendations, declined work, dates, mileages, and repair numbers are retained. These are historical records, not a statement of the vehicle's current condition.

### 2/14/2022 (154065 miles)

REPAIR NUMBER: 0754042

REPORTED BY: Lexus of Westminster

**SERVICE:** OIL AND FILTER - CHANGE

DESCRIPTION: ~|~OIL AND FILTER REPLACEMENT IS DUE ON VEHICLE. ~|~SCHEDULED MAINTENANCE  
~|~154065 PERFORMED OIL AND FILTER CHANGE ON VEHICLE.

**SERVICE:** VEHICLE WAS NOT WASHED DURING SERVICE VISIT.

DESCRIPTION: ~|~UNTIL CAR WASH EMPLOYEE STAFFING LEVELS ARE INCREASED VIA NEW HIRING, LEXUS OF WESTMINSTER IS TEMPORARILY SUSPENDING COMPLIMENTARY CAR WASHES. ~|~

**SERVICE:**

DESCRIPTION: INFLATEDTIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.  
~|~THE TIRES ON YOUR VEHICLE ARE BEING INFLATED TO THE RECOMMENDED AIR PRESSURE DURING THE CURRENT SERVICE VISIT IN COMPLIANCE WITH THE CALIFORNIA GLOBAL WARMING SOLUTIONS ACT OF 2006 (AB32). ~|~

**SERVICE:**

DESCRIPTION: INFLATEDTIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.

**SERVICE:** BULB, REVERSE LIGHT - REPLACE (LABOR ONLY)

DESCRIPTION: ~|~ ~|~,CUSTOMER DECLINED SERVICE

**SERVICE:** ABSORBER, SHOCK/STRUT (REAR) - REPLACE

DESCRIPTION: ~|~ ~|~,CUSTOMER DECLINED SERVICE

**SERVICE:** ELEMENT, AIR CLEANER - REPLACE

DESCRIPTION: ~|~ ~|~,CUSTOMER DECLINED SERVICE

**SERVICE:**

DESCRIPTION: CHECKFOR OIL LEAKING UNDER VEHICLE. INCLUDES CLEAN LEAKING AREA AND VISUALLY INSPECT FOR LEAKS AN ~|~ ~|~,CUSTOMER DECLINED SERVICE

**SERVICE:**

DESCRIPTION: CHECKFOR OIL LEAKING UNDER VEHICLE. INCLUDES CLEAN LEAKING AREA AND VISUALLY INSPECT FOR LEAKS AN

### 7/31/2018 (145338 miles)

REPAIR NUMBER: 0668320

REPORTED BY: Lexus of Westminster

**SERVICE:** OIL AND FILTER - CHANGE

DESCRIPTION: ~|~OIL AND FILTER - CHANGE ~|~ROUTINE MAINTENANCE ~|~145337 COMPLETED OIL & FILTER CHANGE.

**SERVICE:**

DESCRIPTION: INFLATED TIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI. ~|~THE TIRES ON YOUR VEHICLE ARE BEING INFLATED TO THE RECOMMENDED AIR PRESSURE DURING THE CURRENT SERVICE VISIT IN COMPLIANCE WITH THE CALIFORNIA GLOBAL WARMING SOLUTIONS ACT OF 2006 (AB32). ~|~

**SERVICE:**

DESCRIPTION: INFLATED TIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.

**11/5/2017 (140275 miles)**

REPAIR NUMBER: 0647655

REPORTED BY: Lexus of Westminster

**SERVICE:** OIL AND FILTER - CHANGE

DESCRIPTION: ~|~OIL AND FILTER - CHANGE ~|~PERIODIC MAINTENANCE. ~|~140274 PERFORMED OIL AND FILTER SERVICE.

**SERVICE:**

DESCRIPTION: INFLATED TIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI. ~|~THE TIRES ON YOUR VEHICLE ARE BEING INFLATED TO THE RECOMMENDED AIR PRESSURE DURING THE CURRENT SERVICE VISIT IN COMPLIANCE WITH THE CALIFORNIA GLOBAL WARMING SOLUTIONS ACT OF 2006 (AB32). ~|~PSI. ~|~140274 INFLATED TIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.

**SERVICE:**

DESCRIPTION: INFLATED TIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.

**SERVICE:** VEHICLE WAS WASHED DURING SERVICE VISIT.

DESCRIPTION: ~|~AS A WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UPON REQUEST ONLY. WASH TODAY \_\_\_\_ YES \_\_\_\_ NO. ~|~REQUESTED SERVICE. ~|~140274 VEHICLE WAS WASHED AT CURRENT REPAIR VISIT.

**5/29/2017 (135052 miles)**

REPAIR NUMBER: 0634476

REPORTED BY: Lexus of Westminster

**SERVICE:** SERVICE - 135,000 MILES

DESCRIPTION: ~|~SERVICE - 135,000 MILES ~|~CUSTOMER REQUEST ~|~135052 COMPLETED 135K SERVICE TIRES-FRONT 5/32 REAR 5/32 TIRE PSI-35 PS BRAKES- FRONT 8MM REAR 4MM

**SERVICE:** FILL WASHER FLUID RESERVOIR

DESCRIPTION:

**SERVICE:** INSPECT BRAKE PADS AND/OR LININGS, ROTORS AND/OR DRUMS

DESCRIPTION:

**SERVICE:** REPLACE ENGINE OIL

DESCRIPTION:

**SERVICE:** REPLACE ENGINE OIL FILTER

DESCRIPTION:

**SERVICE:** RESET SERVICE INDICATOR

DESCRIPTION:

**SERVICE:** ROAD TEST

DESCRIPTION:

**SERVICE: ROTATE TIRES**

DESCRIPTION:

**SERVICE: RE-TORQUE PROPELLER SHAFT FLANGE BOLTS**

DESCRIPTION:

**SERVICE: INSPECT BODY PAINT AND CORROSION**

DESCRIPTION:

**SERVICE: INSPECT DRIVE AXLE BOOTS**

DESCRIPTION:

**SERVICE: INSPECT DRIVE BELT(S)**

DESCRIPTION:

**SERVICE: INSPECT EXHAUST SYSTEM AND HEAT SHIELDS**

DESCRIPTION:

**SERVICE: INSPECT REAR DIFFERENTIAL FLUID LEVEL**

DESCRIPTION:

**SERVICE: INSPECT SUSPENSION BALL JOINTS**

DESCRIPTION:

**SERVICE: INSPECT STEERING OPERATION AND LINKAGE**

DESCRIPTION:

**SERVICE: INSPECT RACK AND PINION ASSEMBLY**

DESCRIPTION:

**SERVICE: UNABLE TO ADJUST STEERING WHEEL**

DESCRIPTION: ~|~CUST ASK IF WE CAN RAISE STEERING WHEEL UP SLIGHTLY - ADVISE (MOTOR IS BAD) ~|~  
~|~135052 UNABLE TO ADJUST STEERING WHEEL WITH MOTOR MALFUNCTION NO REPAIRS PERFORMED AT THIS TIME

**SERVICE:**

DESCRIPTION: INFLATED TIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.  
~|~THE TIRES ON YOUR VEHICLE ARE BEING INFLATED TO THE RECOMMENDED AIR PRESSURE DURING THE CURRENT SERVICE VISIT IN COMPLIANCE WITH THE CALIFORNIA GLOBAL WARMING SOLUTIONS ACT OF 2006 (AB32). ~|~

**SERVICE:**

DESCRIPTION: INFLATED TIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.

**SERVICE:**

DESCRIPTION: ASA WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UP ~|~AS A WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UPON REQUEST ONLY. WASH TODAY \_\_\_\_ YES \_\_\_\_ NO. ~|~

**SERVICE:**

DESCRIPTION: ASA WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UP

## 2/22/2017 (129933 miles)

REPAIR NUMBER: 0625992

REPORTED BY: Lexus of Westminster

**SERVICE: OIL AND FILTER - CHANGE**

DESCRIPTION: ~|~OIL AND FILTER - CHANGE ~|~CUSTOMER REQUEST ~|~129933 PERFORMED OIL AND FILTER CHANGE

**SERVICE:**

DESCRIPTION: CUSTOMERDECLINED RECOMMENDED SERVICE PER LEXUS MAINTENANCE SCHEDULE. PERFORM OIL AND FILTER CHANG ~|~CUSTOMER DECLINED RECOMMENDED SERVICE PER LEXUS MAINTENANCE SCHEDULE. PERFORM OIL AND FILTER CHANGE ONLY PER CUSTOMER REQUEST ~|~

**SERVICE:**

DESCRIPTION: CUSTOMERDECLINED RECOMMENDED SERVICE PER LEXUS MAINTENANCE SCHEDULE. PERFORM OIL AND FILTER CHANG

**SERVICE:**

DESCRIPTION: THETIRES ON YOUR VEHICLE ARE BEING INFLATED TO THE RECOMMENDED AIR PRESSURE DURING THE CURRENT SE ~|~THE TIRES ON YOUR VEHICLE ARE BEING INFLATED TO THE RECOMMENDED AIR PRESSURE DURING THE CURRENT SERVICE VISIT IN COMPLIANCE WITH THE CALIFORNIA GLOBAL WARMING SOLUTIONS ACT OF 2006 (AB32). ~|~

**SERVICE:**

DESCRIPTION: THETIRES ON YOUR VEHICLE ARE BEING INFLATED TO THE RECOMMENDED AIR PRESSURE DURING THE CURRENT SE

**SERVICE:**

DESCRIPTION: ASA WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UP ~|~AS A WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UPON REQUEST ONLY. WASH TODAY \_\_\_\_ YES \_\_\_\_ NO. ~|~

**SERVICE:**

DESCRIPTION: ASA WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UP

**11/2/2016 (124666 miles)**

REPAIR NUMBER: 0617236

REPORTED BY: Lexus of Westminster

**SERVICE: OIL AND FILTER - CHANGE**

DESCRIPTION: ~|~OIL AND FILTER - CHANGE ~|~REQUESTED SERVICE ~|~124666 30 COMPLETED OIL CHANGE

**SERVICE:**

DESCRIPTION: INFLATEDTIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI. ~|~THE TIRES ON YOUR VEHICLE ARE BEING INFLATED TO THE RECOMMENDED AIR PRESSURE DURING THE CURRENT SERVICE VISIT IN COMPLIANCE WITH THE CALIFORNIA GLOBAL WARMING SOLUTIONS ACT OF 2006 (AB32). ~|~REQUESTED SERVICE ~|~124666 INFLATED TIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.

**SERVICE:**

DESCRIPTION: INFLATEDTIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.

**SERVICE:**

DESCRIPTION: ASA WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UP ~|~AS A WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UPON REQUEST ONLY. WASH TODAY \_\_\_\_ YES \_\_\_\_ NO. ~|~WASH ~|~124666 WASH

**SERVICE:**

DESCRIPTION: ASA WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UP

**SERVICE: LAMP, CENTER STOP - REPLACE (LABOR ONLY)**

DESCRIPTION: ~|~ ~|~,CUSTOMER DECLINED SERVICE -CUSTOMER DECLINED

**SERVICE:** FLUID, DIFFERENTIAL (REAR) - REPLACE

DESCRIPTION: ~|~ ~|~,CUSTOMER DECLINED SERVICE -CUSTOMER DECLINED

**SERVICE:** SYSTEM, BRAKES - FLUSH

DESCRIPTION: ~|~ ~|~,CUSTOMER DECLINED SERVICE -CUSTOMER DECLINED

## 6/5/2016 (119506 miles)

REPAIR NUMBER: 0604487

REPORTED BY: Lexus of Westminster

**SERVICE:** COMPLETED OIL CHANGE

DESCRIPTION: ~|~PERFORM ENGINE OIL & FILTER CHANGE WITH GENUINE LEXUS MOTOR OIL. CHECK & CORRECT TIRE AIR PRESSURE. INCLUDES HAZARDOUS WASTE REMOVAL CHARGE. ~|~CUSTOMER REQUESTED ~|~119506 CUSTOMER REQUESTED 30 COMPLETED OIL & FILTER CHANGE.

**SERVICE:**

DESCRIPTION: INFLATEDTIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI. ~|~THE TIRES ON YOUR VEHICLE ARE BEING INFLATED TO THE RECOMMENDED AIR PRESSURE DURING THE CURRENT SERVICE VISIT IN COMPLIANCE WITH THE CALIFORNIA GLOBAL WARMING SOLUTIONS ACT OF 2006 (AB32). ~|~ ~|~119506 INFLATED TIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.

**SERVICE:**

DESCRIPTION: INFLATEDTIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.

**SERVICE:**

DESCRIPTION: ASA WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UP ~|~AS A WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UPON REQUEST ONLY. WASH TODAY \_\_\_\_ YES \_\_\_\_ NO. ~|~WATER CONSERVATION

**SERVICE:**

DESCRIPTION: ASA WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UP

## 2/4/2016 (114738 miles)

REPAIR NUMBER: 0594936

REPORTED BY: Lexus of Westminster

**SERVICE:** COMPLETED OIL CHANGE

DESCRIPTION: ~|~PERFORM ENGINE OIL & FILTER CHANGE WITH GENUINE LEXUS MOTOR OIL. CHECK & CORRECT TIRE AIR PRESSURE. INCLUDES HAZARDOUS WASTE REMOVAL CHARGE. ~|~REQUESTED SERVICE ~|~114738 COMPLETED OIL & FILTER CHANGE... RECOMMEND REPLACING 4 TIRES.... CUSTOMER DECLINED AT THIS TIME.

**SERVICE:**

DESCRIPTION: INFLATEDTIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI. ~|~THE TIRES ON YOUR VEHICLE ARE BEING INFLATED TO THE RECOMMENDED AIR PRESSURE DURING THE CURRENT SERVICE VISIT IN COMPLIANCE WITH THE CALIFORNIA GLOBAL WARMING SOLUTIONS ACT OF 2006 (AB32). ~|~PSI ~|~114738 INFLATED TIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.

**SERVICE:**

DESCRIPTION: INFLATEDTIRES TO LEXUS RECOMMENDED PRESSURE -- LF 35 PSI, LR 35 PSI, RR 35 PSI, RF 35 PSI.

**SERVICE:**

DESCRIPTION: ASA WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UP ~|~AS A WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UPON REQUEST ONLY. WASH TODAY \_\_\_\_ YES \_\_\_\_ NO. ~|~WATER CONSERVATION ~|~114738 WASH

**SERVICE:**

DESCRIPTION: ASA WATER CONSERVING MEASURE DURING CURRENT EXTREME DROUGHT CONDITIONS, L.O.W. IS WASHING CARS UP

**6/19/2014 (97348 miles)**

REPAIR NUMBER: 0156680

REPORTED BY: Lexus of Cerritos

**SERVICE:** RECOMMENDED MAINT - 00

DESCRIPTION: ~|~PLS CHECK TRANS FLUID AND ADVISE ~|~ ~|~97348 REC DUE TO MILAGE

**SERVICE:**

DESCRIPTION: TECHNICIAN'SMULTI POINT INSPECTION IS EITHER NOT NEEDED AT THIS TIME, OR WILL BE PERFORMED AS PAR ~|~TECHNICIAN'S MULTI POINT INSPECTION IS EITHER NOT NEEDED AT THIS TIME, OR WILL BE PERFORMED AS PART OF MAINTENANCE SERVICE ~|~

**SERVICE:**

DESCRIPTION: TECHNICIAN'SMULTI POINT INSPECTION IS EITHER NOT NEEDED AT THIS TIME, OR WILL BE PERFORMED AS PAR

**SERVICE:** BRAKES GREEN, SEE YOUR SERVICE CONSULTANT ON YOUR NEXT VISIT

DESCRIPTION: TIRE INFLATION SERVICE COMPLETED AND TIRE PRESSURES ARE AS FOLLOW; \_\_\_\_ PSI LF,\_\_\_\_ PSI RF, \_\_\_\_ PSI

**SERVICE:** BATTERY GREEN, CHECKED AND OK AT THIS TIME

DESCRIPTION:

**SERVICE:** TIRES GREEN, PLEASE SEE YOUR SERVICE CONSULTANT AT YOUR NEXT VISIT

DESCRIPTION:

**SERVICE:** RECOMMENDS TRANSMISSION FLUSH \$250.00

DESCRIPTION:

**SERVICE:** RECOMMENDS FRONT LOWER CONTROL ARMS BUSHINGS \$1450.00 PLUS TAX

DESCRIPTION:

**SERVICE:** PERFORM VCP LUBE, OIL AND FILTER SERVICE

DESCRIPTION: ~|~PERFORM VCP LUBE, OIL AND FILTER SERVICE ~|~ ~|~97348 50 LOF SERVICE,34 PSI AND 8/32 TIRE TREAD.FRONT BRAKES 6MM AND REARS 5MM

**12/11/2013 (92373 miles)**

REPAIR NUMBER: 0141051

REPORTED BY: Lexus of Cerritos

**SERVICE:** CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT

DESCRIPTION: ~|~CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT ~|~ ~|~92373

**SERVICE:**

DESCRIPTION: TIREINFLATION SERVICE COMPLETED AND TIRE PRESSURES ARE AS FOLLOW; \_\_\_\_ PSI LF,\_\_\_\_ PSI RF, \_\_\_\_ PSI

**SERVICE:** TIRE(S) REQUIRE REPLACEMENT AT THIS TIME

DESCRIPTION:

**SERVICE:** BRAKES GREEN, SEE YOUR SERVICE CONSULTANT ON YOUR NEXT VISIT

DESCRIPTION:

**SERVICE:** BRAKES GREEN, SEE YOUR SERVICE CONSULTANT ON YOUR NEXT VISIT

DESCRIPTION:

**SERVICE:** TIRE(S) REQUIRE REPLACEMENT AT THIS TIME

DESCRIPTION:

**SERVICE:** TIRES ARE 0/32 VERY DANGEROUS

DESCRIPTION:

**SERVICE:** PERFORM VCP X LUBE, OIL, FILTER AND TIRE ROTATION BLEND

DESCRIPTION: ~|~PERFORM VCP X LUBE, OIL, FILTER AND TIRE ROTATION BLEND ~|~PERFORMED VCP SERVICE  
~|~92373 PERFORMED VCP SERVICE TIRE READINGS LF=0/32LR=0/32RF=0/32RR=0/32 BRAKE READINGS  
FRONT 9.0MM REAR 7.0MM AUTH # 17186882 CLAIM \$28.00

### 8/26/2013 (87892 miles)

REPAIR NUMBER: 0132172

REPORTED BY: Lexus of Cerritos

**SERVICE:** TECHNICIAN'S MULTI POINT INSPECTION IS EITHER NOT NEEDED AT THIS TIME, OR WILL B

DESCRIPTION: ~|~TECHNICIAN'S MULTI POINT INSPECTION IS EITHER NOT NEEDED AT THIS TIME, OR WILL BE  
PERFORMED AS PART OF MAINTENANCE SERVICE ~|~ ~|~87892 BRAKES FRT=9.0 REAR=7.0 TIRES ALL AT 5/32  
ALL 4 TIRES HAS INSIDE EDGE WEAR

**SERVICE:** TIRE INFLATION SERVICE COMPLETED AND TIRE PRESSURES ARE AS FOLLOW; \_\_\_ PSI LF,\_\_\_

DESCRIPTION:

**SERVICE:** BRAKES GREEN, SEE YOUR SERVICE CONSULTANT ON YOUR NEXT VISIT

DESCRIPTION:

**SERVICE:** TIRES YELLOW, TIRES CLOSE TO NEEDING REPLACEMENT AT THIS TIME

DESCRIPTION:

**SERVICE:** BATTERY GREEN, CHECKED AND OK AT THIS TIME

DESCRIPTION:

**SERVICE:** RECOMMEND REPLACE FRONT CONTROL ARMS RECOMMENDED SERVICE - ALIGNMENT

DESCRIPTION:

**SERVICE:** PERFORM VCP LUBE, OIL, FILTER AND TIRE ROTATION

DESCRIPTION: ~|~PERFORM VCP LUBE, OIL, FILTER AND TIRE ROTATION ~|~ ~|~87892 COMPLETE LOF AND  
TIRE ROTATIONDRS 16351048

### 3/3/2013 (82867 miles)

REPAIR NUMBER: 0118798

REPORTED BY: Lexus of Cerritos

**SERVICE:** TECHNICIAN'S MULTI POINT INSPECTION IS EITHER NOT NEEDED AT THIS TIME, OR WILL B

DESCRIPTION: ~|~TECHNICIAN'S MULTI POINT INSPECTION IS EITHER NOT NEEDED AT THIS TIME, OR WILL BE  
PERFORMED AS PART OF MAINTENANCE SERVICE ~|~ ~|~82867 BRAKES FRT=9.5 REAR=7.0 TIES FRT=5/32  
REAR=6/32

**SERVICE:** TIRE INFLATION SERVICE COMPLETED AND TIRE PRESSURES ARE AS FOLLOW; \_\_\_ PSI LF,\_\_\_

DESCRIPTION:

**SERVICE:** BRAKES GREEN, SEE YOUR SERVICE CONSULTANT ON YOUR NEXT VISIT

DESCRIPTION:

**SERVICE:** TIRES GREEN, PLEASE SEE YOUR SERVICE CONSULTANT AT YOUR NEXT VISIT

DESCRIPTION:

**SERVICE:** BATTERY GREEN, CHECKED AND OK AT THIS TIME

DESCRIPTION:

**SERVICE:**

DESCRIPTION: RECOMMENDREPLACE FRONT SHOCKS DUE TO RIGHT FRONT LEAKING \$1,200.00 PLUS ALIGNME  
RECOMMEND REPLACE FRONT LOWER CONTROL ARMS \$981.00 PLUS ALIGNMENT \$129.95

**SERVICE:** PERFORM VCP LUBE, OIL, FILTER AND TIRE ROTATION

DESCRIPTION: ~|~PERFORM VCP LUBE, OIL, FILTER AND TIRE ROTATION ~|~ ~|~82867 COMPLETE LOF AND  
TIRE ROTATIONDRS 15055033

**SERVICE:** DIFFERENCE

DESCRIPTION:

## 12/5/2012 (80586 miles)

REPAIR NUMBER: 0112079

REPORTED BY: Lexus of Cerritos

**SERVICE:** CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT

DESCRIPTION: ~|~CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT  
~|~PERFORMED VCP SERVICE AND TIRE ROTATION ~|~80586 PERFORMED VCP SERVICE AND TIRE ROTATION  
TIRE READINGS LF=7/32LR=7/32RF=7/32RR=7/32B RAKE READINGS FRONT 9.5MM REAR 9.0MM

**SERVICE:** TIRE INFLATION SERVICE COMPLETED AND TIRE PRESSURES ARE AS FOLLOW; \_\_\_ PSI LF,\_\_\_

DESCRIPTION:

**SERVICE:** TIRES GREEN, PLEASE SEE YOUR SERVICE CONSULTANT AT YOUR NEXT VISIT

DESCRIPTION:

**SERVICE:** BRAKES GREEN, SEE YOUR SERVICE CONSULTANT ON YOUR NEXT VISIT

DESCRIPTION:

**SERVICE:** BATTERY GREEN, CHECKED AND OK AT THIS TIME

DESCRIPTION:

**SERVICE:** TRANSMISSION FLUSH RECOMMENDED - CUSTOMER DECLINED

DESCRIPTION:

**SERVICE:** RECOMMENDED SERVICE - AIR FILTER CHECK/REPLACE

DESCRIPTION:

**SERVICE:** RECOMMENDED SERVICE - A/C CABIN FILTER

DESCRIPTION:

**SERVICE:** RECOMMENDED SERVICE - E.F.I. SERVICE

DESCRIPTION:

**SERVICE:** WIPER INSERTS

DESCRIPTION:

**SERVICE:** DIFF SERVICE

DESCRIPTION:

**SERVICE:** BRAKE FLUSH

DESCRIPTION:

**SERVICE:** PERFORM VCP X LUBE, OIL, FILTER AND TIRE ROTATION BLEND

DESCRIPTION: ~|~PERFORM VCP X LUBE, OIL, FILTER AND TIRE ROTATION BLEND ~|~PERFORMED VCP SERVICE AND ROTATION ~|~80586 PERFORMED VCP SERVICE AND ROTATION PERFORMED VCP SERVICE AUTH# 14456555 CLAIM \$28.00

## 5/13/2012 (75439 miles)

REPAIR NUMBER: 0096398

REPORTED BY: Lexus of Cerritos

**SERVICE:** CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT

DESCRIPTION: ~|~CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT

**SERVICE:** TIRE INFLATION SERVICE COMPLETED AND TIRE PRESSURES ARE AS FOLLOW; \_\_\_ PSI LF,\_\_\_

DESCRIPTION:

**SERVICE:** TIRES GREEN, PLEASE SEE YOUR SERVICE CONSULTANT AT YOUR NEXT VISIT

DESCRIPTION:

**SERVICE:** BRAKES GREEN, SEE YOUR SERVICE CONSULTANT ON YOUR NEXT VISIT

DESCRIPTION:

**SERVICE:** BATTERY GREEN, CHECKED AND OK AT THIS TIME

DESCRIPTION:

**SERVICE:** PERFORM VCP X LUBE, OIL, FILTER AND TIRE ROTATION BLEND

DESCRIPTION: ~|~PERFORM VCP X LUBE, OIL, FILTER AND TIRE ROTATION BLEND ~|~PERFORMED VCP SERVICE WITH ROTATION. ~|~75439 PERFORMED VCP SERVICE WITH ROTATION. AUTH# 12986147 CLAIM \$28.00 TIRE READINGS LF=7/32LR=7/32RF=7/32RR=7/32 BRAKE READINGS FRONT 8.5MM REAR 8.5MM

## 12/21/2011 (70557 miles)

REPAIR NUMBER: 0086256

REPORTED BY: Lexus of Cerritos

**SERVICE:**

DESCRIPTION: MOVEDTO: 86256C LINE: A ~|~MOVED TO: 86256C LINE: A

**SERVICE:**

DESCRIPTION: MOVEDTO: 86256C LINE: A MOVED TO: 86256C LINE: A MOVED TO: 86256C LINE: A MOVED TO: 86256C LINE: A MOVED TO: 86256C LINE: A MOVED TO: 86256C LINE: A

**SERVICE:** MOVED TO: 86256C LINE: B

DESCRIPTION: ~|~MOVED TO: 86256C LINE: B

**SERVICE:** MOVED TO: 86256C LINE: C

DESCRIPTION: ~|~MOVED TO: 86256C LINE: C

**SERVICE:** PERFORM VCP LUBE, OIL AND FILTER SERVICE

DESCRIPTION: ~|~PERFORM VCP LUBE, OIL AND FILTER SERVICE ~|~LOF ~|~70557 LOF 40 FRONT BRAKE 3MM AND REAR BRAKE 9MM..TIRES 8/32..OIL AND FILTER CHANGE, INSTALL NEW DRAIN PLUG WASHER..ADJUST TIRE PRESSURE AND TOP OFF FLUID LEVEL..COMPLETED

## 12/20/2011 (70557 miles)

REPAIR NUMBER: 086256C

REPORTED BY: Lexus of Cerritos

**SERVICE:** TECHNICIAN'S MULTI POINT INSPECTION IS EITHER NOT NEEDED AT THIS TIME, OR WILL B  
DESCRIPTION: ~|~TECHNICIAN'S MULTI POINT INSPECTION IS EITHER NOT NEEDED AT THIS TIME, OR WILL BE  
PERFORMED AS PART OF MAINTENANCE SERVICE

**SERVICE:** TIRE INFLATION SERVICE COMPLETED AND TIRE PRESSURES ARE AS FOLLOW; \_\_\_ PSI LF,\_\_\_  
DESCRIPTION:

**SERVICE:** BRAKES RED, BRAKES REQUIRE REPLACEMENT AT THIS TIME  
DESCRIPTION:

**SERVICE:** TIRES GREEN, PLEASE SEE YOUR SERVICE CONSULTANT AT YOUR NEXT VISIT  
DESCRIPTION:

**SERVICE:** BATTERY GREEN, CHECKED AND OK AT THIS TIME  
DESCRIPTION:

**SERVICE:** RECOMEMNDS FRONT BRAKES SOON !! AT 3MM HITTING SENSOR IF WAITS TOO LONG WILL NEE  
DESCRIPTION:

**SERVICE:** ELEMENT, AIR CLEANER - REPLACE  
DESCRIPTION: ~|~ELEMENT, AIR CLEANER - REPLACE ~|~AIR FILTER DIRTY ~|~70557 AIR FILTER DIRTY 40  
REPLACE AIR FILTER COMPLETED

**SERVICE:** MICROFILTER - REPLACE  
DESCRIPTION: ~|~MICROFILTER - REPLACE ~|~A/C FILTER DIRTY ~|~70557 A/C FILTER DIRTY 30 REPLACE A/C  
FILTER COMPLETED

## 6/23/2011 (65645 miles)

REPAIR NUMBER: 0073117

REPORTED BY: Lexus of Cerritos

**SERVICE:** RECOMMENDED MAINT - 00  
DESCRIPTION: ~|~WAITER DG

**SERVICE:** AUTONATION PRE-PAID MAINTENANCE ; REPLACE ENGINE OIL & FILTER, ROTATE TIRES OR P  
DESCRIPTION: ~|~SERVICE - 65,000 MILES ~|~ ~|~65645 SERVICE PERFORMED 65K MILES SERVICE  
MAINTENANCE. F/BRK. PADS 6MM, R/BRK. PADS 3-4MM LOW AND F & R TIRES 9/32.

**SERVICE:** REPLACE ENGINE OIL  
DESCRIPTION:

**SERVICE:** REPLACE ENGINE OIL FILTER  
DESCRIPTION:

**SERVICE:** RESET SERVICE INDICATOR  
DESCRIPTION:

**SERVICE:** ROAD TEST  
DESCRIPTION:

**SERVICE:** ROTATE TIRES  
DESCRIPTION:

**SERVICE:** INSPECT BRAKE PADS AND/OR LININGS, ROTORS AND/OR DRUMS  
DESCRIPTION:

**SERVICE:** CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT  
 DESCRIPTION: ~|~CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT ~|~  
 ~|~65645 INSPECTION.

**SERVICE:** TIRE INFLATION SERVICE COMPLETED AND TIRE PRESSURES ARE AS FOLLOW; \_\_\_ PSI LF,\_\_\_  
 DESCRIPTION:

**SERVICE:** RECOMMENDED SERVICE - REAR BRAKES  
 DESCRIPTION: ~|~RECOMMENDED SERVICE - REAR BRAKES

## 12/21/2010 (60969 miles)

REPAIR NUMBER: 0058350  
 REPORTED BY: Lexus of Cerritos

**SERVICE:** AUTONATION PRE-PAID MAINTENANCE ; REPLACE ENGINE OIL & FILTER, ROTATE TIRES OR P  
 DESCRIPTION: ~|~AUTONATION PRE-PAID MAINTENANCE ; REPLACE ENGINE OIL & FILTER, ROTATE TIRES OR  
 PLACE BEST TIRES IN FRONT. BILL TO AUTONATION.

**SERVICE:** CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT  
 DESCRIPTION: ~|~CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT

**SERVICE:** 0  
 DESCRIPTION:

**SERVICE:** RECOMMENDED SERVICE - 60K SERVICE  
 DESCRIPTION:

**SERVICE:** REAR BRAKES 3MM REMAINING.  
 DESCRIPTION:

**SERVICE:** BATTERY RED, REQUIRES REPLACEMENT AT THIS TIME  
 DESCRIPTION:

**SERVICE:** TIRES GREEN, PLEASE SEE YOUR SERVICE CONSULTANT AT YOUR NEXT VISIT  
 DESCRIPTION:

**SERVICE:** RECOMMEND REAR BRAKES 360. RECOMMEND BATTERY REPL 196. RECOMMEND 60,000 MILE SER  
 DESCRIPTION:

## 6/27/2010 (55675 miles)

REPAIR NUMBER: 0044509  
 REPORTED BY: Lexus of Cerritos

**SERVICE:** CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT  
 DESCRIPTION: ~|~CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT ~|~  
 ~|~55675 RECOMMEND 4 TIRES AND ALIGNMENT SOON. AT 2/32 AT THE EDGES. REAR BRAKE SOON AT 4MM,  
 FRONT AT 5MM. 60,000 MILE SERVICE AT NEXT SERVICE.

**SERVICE:** --RECOMMENDS 4 TIRES AND ALIGNMENT  
 DESCRIPTION:

**SERVICE:** BRAKES RED, BRAKES REQUIRE REPLACEMENT AT THIS TIME  
 DESCRIPTION:

**SERVICE:** BATTERY GREEN, CHECKED AND OK AT THIS TIME  
 DESCRIPTION:

**SERVICE:** PERFORM LEASE BUY OUT INSPECTION AS PER SALES DEPARTMENT  
 DESCRIPTION: ~|~PERFORM LEASE BUY OUT INSPECTION AS PER SALES DEPARTMENT ~|~ ~|~55675

PERFORMED LEASE BUY OUT INSPECTION.

**SERVICE:** SMOG INSPECTION

DESCRIPTION: ~|~SMOG INSPECTION ~|~ ~|~55675 PERFORMED SMOG INSPECTION, ISSUE SMOG CERT# WL298814

## 6/8/2010 (55212 miles)

REPAIR NUMBER: 0042962

REPORTED BY: Lexus of Cerritos

**SERVICE:** DEFAULT

DESCRIPTION: ~|~55000 MILE SERVICE - 00 ~|~ ~|~55212 SERVICE DUE PERFORMED 55,000 MILE SERVICE COMPLETE FRONT BRAKE AT 8.0MM REAR AT 5.0MM TIRE CONDITION 4/32 WORN ON EDGE

**SERVICE:** CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT

DESCRIPTION: ~|~CUSTOMER REQUESTED TO HAVE MULTI POINT INSPECTION PERFORMED THIS VISIT

**SERVICE:** TIRES YELLOW, TIRES CLOSE TO NEEDING REPLACEMENT AT THIS TIME

DESCRIPTION:

**SERVICE:** REAR BRAKE, MAY NEED REPLACEMENT NEXT SERVICE.

DESCRIPTION:

**SERVICE:** MAINTENANCE - 01

DESCRIPTION: ~|~[phone number omitted for privacy]

## 12/25/2009 (50562 miles)

REPAIR NUMBER: 0430169

REPORTED BY: Lexus of Westminster

**SERVICE:** REPAIR TIRE PUNCTURE - REMOVE TIRE, PREP. & APPLY PATCH, REMOUNT & BALANCE TIRE, R

DESCRIPTION: ~|~CUST STATES: LOW TIRE WARNING LAMP ON. ADVISE ~|~SCREW IN TIRE ~|~COMPLETED REPAIR TO RIGHT REAR TIRE.

**SERVICE:** 50K SERVICE

DESCRIPTION: ~|~REPLACE ENGINE OIL AND FILTER, ROAD TEST VEHICLE, ROTATE TIRES (IF APPLICABLE), VISUALLY INSPECT BRAKE PADS AND DISCS, INSPECT ENGINE COOLANT, RE-TORQUE DRIVE SHAFT FLANGE BOLTS (IF APPLICABLE), INSPECT BALL JOINTS AND DUST COVERS, INSPECT BODY, INSPECT ~|~REQUESTED SERVICE ~|~FRONT BRAKES 8MM/REAR BRAKES 4MM REMAINING PAD REPLACEMENT DUE AT 2.5MM OR BELOW. FOUND ENGINE BATTERY WEAK AT THIS TIME.

**SERVICE:** REPLACE CABIN AIR FILTER

DESCRIPTION: ~|~REPLACE CABIN AIR FILTER ~|~REQUESTED SERVICE ~|~REPLACED AC FILTER.

## 6/30/2009 (45231 miles)

REPAIR NUMBER: 0416306

REPORTED BY: Lexus of Westminster

**SERVICE:** 45K SERVICE

DESCRIPTION: ~|~REPLACE ENGINE OIL AND FILTER, ROAD TEST VEHICLE, ROTATE TIRES (IF APPLICABLE), VISUALLY INSPECT BRAKE PADS AND DISCS, INSPECT ENGINE COOLANT, RE-TORQUE DRIVE SHAFT FLANGE BOLTS (IF APPLICABLE), INSPECT BALL JOINTS AND DUST COVERS, INSPECT BODY, INSPECT ~|~REQUESTED SERVICE ~|~FRONT BRAKES 9MM/REAR BRAKES 4MM REMAINING PAD REPLACEMENT DUE AT 2.5MM OR BELOW. REPLACED ENGINE AIR FILTER. RECOMMEND REAR BRAKES AT NEXT SERVICE

**SERVICE:** REPLACE ENGINE AIR FILTER

DESCRIPTION:

**10/15/2008 (35903 miles)**

REPAIR NUMBER: 0395271

REPORTED BY: Lexus of Westminster

**SERVICE:** 35K SERVICE COMPLETE

DESCRIPTION: ~|~REPLACE ENGINE OIL AND FILTER, ROAD TEST VEHICLE, ROTATE TIRES (IF APPLICABLE ), VISUALLY INSPECT BRAKE PADS AND DISCS, INSPECT ENGINE COOLANT, RE-TORQUE DRIVE SHAFT FLANGE BOLTS (IF APPLICABLE), INSPECT BALL JOINTS AND DUST COVERS , INSPECT BODY, INSPECT ~|~SERVICE REQUESTED. ~|~FRONT BRAKES 2.8MM/REAR BRAKES 5.0MM REMAINING. RECOMMEND REPLACING PADS AT 3.0MM OR BELOW. \*\*\* RECOMMEND ALIGNMENT. CUSTOMER DECLINED. NOTE: RIGHT FRONT TIRE HAS CUP ON SIDEWALLS ARE DAMAGED. RECOMMEND FRONT BRAKES ASAP

**SERVICE:** INSPECTION

DESCRIPTION: ~|~PLEASE CHECK FOR BAD A/C SMELL ~|~ ~|~USE OF AUTO FUNCTION AND FRESH AIR TO HALF TO REDUCE CHANCE OF ODOR. NO REPAIR NEEDED AT THIS TIME.

**6/4/2008 (30763 miles)**

REPAIR NUMBER: 0383954

REPORTED BY: Lexus of Westminster

**SERVICE:** MINIMUM RECOMMENDED SERVICE COMPLETED

DESCRIPTION: ~|~REPLACE ENGINE OIL AND FILTER, ROAD TEST VEHICLE, ROTATE TIRES (IF APPLICABLE ), VISUALLY INSPECT BRAKE PADS AND DISCS, INSPECT ENGINE COOLANT, RE-TORQUE DRIVE SHAFT FLANGE BOLTS (IF APPLICABLE), INSPECT BALL JOINTS AND DUST COVERS , INSPECT BODY, INSPECT ~|~REQUESTED SERVICE. ~|~FRT BRAKES 4.5MM AND REAR 5.5MM REMAINING. COMPLETED SERVICE.

**SERVICE:** REPLACE ENGINE AIR FILTER

DESCRIPTION: ~|~REPLACE ENGINE AIR FILTER ~|~REQUESTED SERVICE. ~|~REPLACED AIR FILTER.

**SERVICE:** DRAIN, FLUSH, REFILL AND BLEED BRAKE HYDRAULIC SYSTEM

DESCRIPTION: ~|~DRAIN, FLUSH, REFILL AND BLEED BRAKE HYDRAULIC SYSTEM ~|~REQUESTED SERVICE. ~|~COMPLETED BRAKE FLUID FLUSH.

**SERVICE:** REPLACE CABIN AIR FILTER

DESCRIPTION: ~|~REPLACE CABIN AIR FILTER ~|~REQUESTED SERVICE. ~|~REPLACED AC FILTER.

**SERVICE:** COMPUTER BALANCE ALL WHEELS

DESCRIPTION: ~|~COMPUTER BALANCE ALL WHEELS ~|~REQUESTED SERVICE. ~|~BALANCED WHEELS.

**1/10/2008 (25236 miles)**

REPAIR NUMBER: 0370446

REPORTED BY: Lexus of Westminster

**SERVICE:** MINIMUM RECOMMENDED SERVICE COMPLETED

DESCRIPTION: ~|~REPLACE ENGINE OIL AND FILTER, ROAD TEST VEHICLE, ROTATE TIRES (IF APPLICABLE ), VISUALLY INSPECT BRAKE PADS AND DISCS, INSPECT ENGINE COOLANT, RE-TORQUE DRIVE SHAFT FLANGE BOLTS (IF APPLICABLE), INSPECT BALL JOINTS AND DUST COVERS , INSPECT BODY, INSPECT ~|~RECOMMENDED SERVICE ~|~SERVICE COMPLETED FRONT BRAKES 5MM/REAR BRAKES 6MM REMAINING. RECOMMEND REPLACING PADS AT 3.0MM OR BELOW

## 8/28/2007 (20435 miles)

REPAIR NUMBER: 0357548

REPORTED BY: Lexus of Westminster

**SERVICE:** 20K SERVICE COMPLETE

DESCRIPTION: ~|~REPLACE ENGINE OIL AND FILTER, ROAD TEST VEHICLE, ROTATE TIRES (IF APPLICABLE ), VISUALLY INSPECT BRAKE PADS AND DISCS, INSPECT ENGINE COOLANT, RE-TORQUE DRIVE SHAFT FLANGE BOLTS (IF APPLICABLE), INSPECT BALL JOINTS AND DUST COVERS , INSPECT BODY, INSPECT ~|~SERVICE REQUESTED. ~|~FRONT BRAKES 7.0MM/REAR BRAKES 7.0MM REMAINING. RECOMMEND REPLACING PADS AT 2.5MM OR BELOW.

**SERVICE:** REPLACE CABIN AIR FILTER

DESCRIPTION: ~|~REPLACE CABIN AIR FILTER ~|~SERVICE REQUESTED. ~|~REPLACED A/C FILTER.

**SERVICE:** REPLACE TWO WIPER INSERTS

DESCRIPTION: ~|~REPLACE TWO WIPER INSERTS ~|~SERVICE REQUESTED. ~|~REPLACED WIPER BLADE INSERTS.

**SERVICE:** REPLACE ENGINE AIR FILTER

DESCRIPTION: ~|~REPLACE ENGINE AIR FILTER ~|~SERVICE REQUESTED. ~|~REPLACED ENGINE AIR FILTER.

## 4/5/2007 (14544 miles)

REPAIR NUMBER: 0343568

REPORTED BY: Lexus of Westminster

**SERVICE:** 15,000 MILE INSPECTION LS400'430 MODELS,CHANGE ENGINE OIL & FILTER,CHECK & CORRE

DESCRIPTION: ~|~15,000 MILE INSPECTION LS400'430 MODELS,CHANGE ENGINE OIL & FILTER,CHECK & CORRECT ALL FLUID LEVELS,ROTATE TIRES,SET TIRE PRESSURE TO 32 PSI,INSPECT EXHAUST,DRIVE AXLE BOOTS,STEERING & SUSPENSION,INSPECT FAN BELTS AND HOSES,INSPECT BRAKES,XXXXXXXX XXXXXXXX ~|~REQUESTED SERVICE ~|~FRT BRAKES 7.0MM ANDA REAR 7.0MM REMAINING REPLACED AC FILTER

## 1/16/2007 (9447 miles)

REPAIR NUMBER: 0335387

REPORTED BY: Lexus of Westminster

**SERVICE:** LUBE OIL & FILTER CHANGE AND CORRECT ALL FLUID LEVELS ESTIMATE \$49.95 (INCLUDES

DESCRIPTION: ~|~LUBE OIL & FILTER CHANGE AND CORRECT ALL FLUID LEVELS ESTIMATE \$49.95 (INCLUDES HAZARDOUS WASTE REMOVAL CHARGE OF \$1.00)

## 11/5/2006 (5587 miles)

REPAIR NUMBER: 0328218

REPORTED BY: Lexus of Westminster

**SERVICE:** COMPLETED 5,000 MILE SERVICE

DESCRIPTION: ~|~5K SERVICE-WARRANTY-8 CYLINDER MODELS,CHANGE ENGINE OIL AND FILTER,CHECK AND CORRECT FLUIDS,ROTATE TIRES AND SET TIRE PRESSURE TO 32 PSI.,INSPECT EXAUST,DRIVE AXLE BOOTS,STEERING AND SUSPENSION,INSPECT BRAKES,ROAD TEST,WASH CAR. ~|~CUSTOMER REQUEST ~|~COMPLETED SERVICE FRONT BRAKES @ 9.5MM REAR BRAKES @ 9.0MM REPLACE @ 3.0MM

## 6/4/2006 (8 miles)

REPAIR NUMBER: 0067627

REPORTED BY: Longo Lexus

**SERVICE:** PERFORMED NEW CAR DETAIL WITH SIMONIZ APPLICATION

DESCRIPTION: ~|~PERFORM NEW CAR DETAIL WITH SIMONIZ APPLICATION

~|~===== ~|~PERFORMED NEW CAR DETAIL WITH SIMONIZ APPLICATION

**SERVICE:** PERFORMED PRE-DELIVERY INSPECTION

DESCRIPTION: ~|~PERFORM PRE-DELIVERY INSPECTION ~|~PDI ~|~PERFORMED PRE-DELIVERY INSPECTION