6/24/2026 (139619 miles)

REPAIR NUMBER: 6039471
REPORTED BY: Rydell Toyota of Grand Forks

SERVICE: ADVANCED LEVEL 3 DIAGNOSIS
DESCRIPTION: ~|~REAR AIR RIDE SEEMS TO BE VERY HARD WHEN DRIVING AND GOING OVER BUMPS ABOUT 3 MONTHS AGO. SEEMS TO BE INTERMITTENT. CHECK & ADVISE POSSIBLE TECH TO RIDE WITH GUEST. ~|~ ~|~UNABLE TO DUPLICATE CUSTOMER CONCERN

SERVICE: MULTIPOINT INSPECTION
DESCRIPTION: ~|~ ~|~NO CAUSE SPECIFIED IN RO ~|~PERFORMED MULTIPOINT INSPECTION 00RBA (411 0.2)

SERVICE: PUT UNDER BRADY
DESCRIPTION: ~|~PUT UNDER BRADY ~|~

10/22/2019 (73435 miles)

REPAIR NUMBER: 0158708
REPORTED BY:

SERVICE: LUBE OIL AND FILTER CHANGE/ CAR *SYNTHETIC*
DESCRIPTION: ~|~LUBE OIL AND FILTER CHANGE/ CAR *SYNTHETIC* ~|~MAINTENANCE

SERVICE:
DESCRIPTION: RE-SETMAINT LIGHT, PLEASE INSPECT FOR FLEX FUEL AND CABIN FILTER ON TOYOTA CARE VEHICLES. ~|~RE-SET MAINT LIGHT, PLEASE INSPECT FOR FLEX FUEL AND CABIN FILTER ON TOYOTA CARE VEHICLES. ~|~

SERVICE:
DESCRIPTION: RE-SETMAINT LIGHT, PLEASE INSPECT FOR FLEX FUEL AND CABIN FILTER ON TOYOTA CARE VEHICLES.

SERVICE:
DESCRIPTION: PERFORMCOURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE P ~|~PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE PRESSURE TO SPEC'S ~|~

SERVICE:
DESCRIPTION: PERFORMCOURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE P

6/19/2017 (63374 miles)

REPAIR NUMBER: 0132504
REPORTED BY:

SERVICE: LUBE OIL AND FILTER CHANGE
DESCRIPTION: ~|~LUBE OIL AND FILTER CHANGE ~|~ ~|~63374 CHANGED OIL AND FILTER

SERVICE:
DESCRIPTION: PERFORMCOURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE P ~|~PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE PRESSURE TO SPEC'S ~|~

SERVICE:
DESCRIPTION: PERFORMCOURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE P

5/26/2016 (58038 miles)

REPAIR NUMBER: 0120933
REPORTED BY:

SERVICE: LUBE OIL AND FILTER CHANGE
DESCRIPTION: ~|~LUBE OIL AND FILTER CHANGE ~|~ ~|~58038 CHANGED OIL AND FILTER

SERVICE:
DESCRIPTION: PERFORMCOURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE P ~|~PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE PRESSURE TO SPEC'S ~|~ ~|~58038 VEHICLE OK AT THIS TIME

SERVICE:
DESCRIPTION: PERFORMCOURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE P

4/19/2015 (53360 miles)

REPAIR NUMBER: 0108778
REPORTED BY:

SERVICE: LUBE OIL AND FILTER CHANGE
DESCRIPTION: ~|~LUBE OIL AND FILTER CHANGE ~|~ ~|~53360 OIL CHANGE COMPLETE

SERVICE:
DESCRIPTION: PERFORMCOURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE P ~|~PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE PRESSURE TO SPEC'S ~|~ ~|~53360 INSPECTION COMPLETE

SERVICE:
DESCRIPTION: PERFORMCOURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE P

10/7/2013 (47952 miles)

REPAIR NUMBER: 0091959
REPORTED BY:

SERVICE: LUBE OIL AND FILTER AND 27 POINT SAFETY INSPECTION
DESCRIPTION: ~|~LUBE OIL AND FILTER AND 27 POINT SAFETY INSPECTION

SERVICE: PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIR
DESCRIPTION: ~|~PERFORM COURTESY VEHICLE INSPECTION. INCLUDES: VISUAL INSPECTION OF VEHICLE, TIRES, AND SET TIRE PRESSURE TO SPEC'S

9/30/2013 (47523 miles)

REPAIR NUMBER: 0517020
REPORTED BY:

SERVICE: CHECK OUT AND REPLACE RIGHT FRONT WHEEL BEARING ASSEMBLY
DESCRIPTION: ~|~CUSTOMER STATES NOISE FROM WHEEL BEARING DROPPING OFF CAR COUPLE DAYS

SERVICE: LEXUS OF WAYZATA VISUAL VEHICLE INSPECTION
DESCRIPTION: ~|~LEXUS OF WAYZATA VISUAL VEHICLE INSPECTION

7/26/2013 (45914 miles)

REPAIR NUMBER: 0509911
REPORTED BY:

SERVICE: DIAGNOSED DYBAMIC CRUISE UNIT FAILURE - GUEST ADVISED
DESCRIPTION: ~|~CUSTOMER STATES VSC LIGHT ON - CRUISE INOP

SERVICE: LEXUS OF WAYZATA VISUAL VEHICLE INSPECTION
DESCRIPTION: ~|~LEXUS OF WAYZATA VISUAL VEHICLE INSPECTION

SERVICE: REPLACE FRONT BRAKE PADS CLEAN AND LUBRICATE CALIPERS RESURFACE FRONT ROTORS CHE
DESCRIPTION: ~|~REPLACE FRONT BRAKE PADS CLEAN AND LUBRICATE CALIPERS RESURFACE FRONT ROTORS CHECK AND ADJUST PARK BRAKE ********** ** REAR BRAKE PAD LEFT %_____

SERVICE: REPLACE REAR BRAKE PADS CLEAN AND LUBRICATE CALIPERS RESURFACE REAR ROTORS CHECK
DESCRIPTION: ~|~REPLACE REAR BRAKE PADS CLEAN AND LUBRICATE CALIPERS RESURFACE REAR ROTORS CHECK AND ADJUST PARK BRAKE ********** **

7/31/2008 (27318 miles)

REPAIR NUMBER: 0301839
REPORTED BY:

SERVICE: NOTE
DESCRIPTION: ~|~SOP HERE-TECH 238

SERVICE: INSPECT - SCRATCHES TO DEEP - WILL TRY TO LIGHTEN UP - WILL NEED BODYSHOP
DESCRIPTION: ~|~TRY TO BUFF SCTRATCH ASK CUSTOMER

SERVICE: SUPREME VEHICLE WASH
DESCRIPTION: ~|~SUPREME VEHICLE WASH

SERVICE: CHANGE OIL AND FILTER CARS AND RX MODELS, INSPECT FLUID LEVELS,CHECK TIRE PRESSU
DESCRIPTION: ~|~CHANGE OIL AND FILTER CARS AND RX MODELS, INSPECT FLUID LEVELS,CHECK TIRE PRESSURES,INSPECT BELTS,RESET MAINT REMINDER LIGCAR WASH ~|~ ~|~27318 COMPLETE OIL CHANGE SERVICE. ALL BRAKES AT 90% PAD LEFT. ALL TIRES AT 7/32NDS.

SERVICE: DETAIL NOTE
DESCRIPTION: ~|~TRY AND BUFF SCRATCH ON ON BOTH DRIVERS SIDE DOORS

SERVICE: F. DR TRIM PNL ASSY/RETAINER
DESCRIPTION: ~|~THE PASSENGER DOOR PANEL IS PULLING APART ~|~FOUND POOR FIT OF PASSENGER DOOR PANEL. ~|~27318 REPLACED PASSENGER DOOR PANEL.

SERVICE: OUTER REAR VIEW MIRROR ASSY (REMOTE CONTROL TYPE)
DESCRIPTION: ~|~THE PASSENGER MIRROR DOES NOT ADJUST SIDE TO SIDE ~|~FOUND OPEN CIRCUIT IN PASSENGER MIRROR. ~|~27318 REPLACED PASSENGER SIDER OUTER MIRROR ASSEMBLY.

7/6/2008 (26208 miles)

REPAIR NUMBER: 0298163
REPORTED BY:

SERVICE: ROTATE TIRES
DESCRIPTION: ~|~ROTATE TIRES ~|~ ~|~26208 ROTATED TIRES COMPLETED

SERVICE: IT WAS NECCESSARY TO SPECIAL ORDER A PART FOR YOUR CAR. PARTS GENERALLY ARRIVE I
DESCRIPTION: ~|~THE PASSENGER FRONT DOOR ARM REST IS PULLING APART

SERVICE: IT WAS NECCESSARY TO SPECIAL ORDER A PART FOR YOUR CAR. PARTS GENERALLY ARRIVE I
DESCRIPTION: ~|~THE PASSENGER MIRROR DOES NOT ADJUST SIDE TO SIDE ~|~F

5/24/2007 (16538 miles)

REPAIR NUMBER: 0244702
REPORTED BY:

SERVICE: 15000 MILE INTERVAL SERVICE. SEE ATTACHED SHEET FOR DETAILED DESCRIPTION.
DESCRIPTION: ~|~15000 MILE INTERVAL SERVICE. SEE ATTACHED SHEET FOR DETAILED DESCRIPTION.

SERVICE: ALIGNMENT NOT DONE
DESCRIPTION: ~|~FOUR WHEEL SUSPENSION ALIGNMENT SET CASTER, CAMBER, AND TOE IN CHECK THRUST ANGLE

12/26/2005 (5791 miles)

REPAIR NUMBER: 0184844
REPORTED BY:

SERVICE: COMPLIMENTARY 5000 MILE SERVICE INCLUDING OIL AND FILTER CHANGE WITH ROTATION OF
DESCRIPTION: ~|~COMPLIMENTARY 5000 MILE SERVICE INCLUDING OIL AND FILTER CHANGE WITH ROTATION OF TIRES ~|~MT

8/8/2005 (10 miles)

REPAIR NUMBER: 0222764
REPORTED BY:

SERVICE: PRE-DELIVERY SERVICE FOR USA ALL ALTITUDES
DESCRIPTION: ~|~PERFORM THE PRE-DELIVERY INSPECTION PER THE MANUFACTURERS CHECKLIST. ~|~ ~|~COMPLETED PRE DELIVERY INSPECTION PER THE MANUFACTURERS